Bus Mouse Connections





Signal name.	MPS Din Jack.
+5v	1
XDA (X axis displacement signal A)	2
XDB (X axis displacement signal B)	3
YDA (Y axis displacement signal A)	4
YDB (Y axis displacement signal B)	5
LB (signal from left mouse button)	6
MB (signal from middle mouse button)	7
RB (signal from right mouse button)	8
Ground	9

The information contained upon this page is supplied in good faith, and to the best of my knowledge is accurate. However, I accept no responsibility for damage or injury, however caused, due to the use of this data.